FORM **USE PREVIOUS** 2820 **EDITIONS** Approved For Release 2002/97#160 MASRD975B00326R000100200030405A DD/SA D/SA FILE INFO Nov 197352625 REPRODUCTION PROHIBITED 16 ACTION 17 7 12 18 13 8 14 19 4 9 15 2Ø 1Ø 25X1 SECRET 190751Z NOV 73 CITE 25X1 25X1 INFO IDEALIST TACKLE RYBAT RYBAT 25X1 FOR BRIG GEN BEVAN AND MR FLITCROFT FROM 25X1 25X1 REF SUBJ: MISSION NO C-353-C WE HAVE HAD SEVERAL CRITIQUES OF MISSION C-353C IN AN EFFORT TO DETERMINE WHY THE PILOT DEVIATED FROM TRACK. HE HAS REPEATEDLY SAID HE DOES NOT KNOW WHAT HE DID BUILD FEELS HE MAY HAVE SELECTED THE WRONG HEADING, INITIATED AN AUTOPILOT TURN AND BECAME PRE-OCCUPIED IN THE COCKPIT FILLING OUT THE FLT LOG. THE FOREGOING WAS ONE OF OUR CONJECTURES AND MAY POSSIBLY HAVE INFLUENCED HIS THOUGHTS. I DON'T FEEL TPX COURSE DEVIATIONS WERE INTENTIONAL. I BELIEVE THE PILOT MISREAD THE FLT LOG. SELECTED 288 DEGREES 25X1

25X1 TAPES CONFIRM 287.5 DEG) VICE 228 DEGREES, ENGAGED THE

AUTOPILOT TURN MODE (BUG TURN) AND BECAME PREOCCUPIED WITH UP-DATING HIS FLT LOG.

TO CLARIFY. THE HEADING TO PT. AK IS 228 DEGREES AND SUBSEQUENT ENTRY ON THE FLT LOG IS ALSO 228 DEGREES TO PT AL. I BELIEVE THE PILOT FELT HE HAD COMPLETED THE LEG AJ-AK AND THROUGH HABIT

Approved For Belease 2002/03/1#0EICIAERDR75B00326R000100200030-0

		REPRODUCTI	ON PROHIBITED	
ACTION	1	6	11	16
	3	7 8	12	17
	4	9	14	19
	5	1ø	15	2,0
	WHAT HE TH		EXT HEADING, ALT	
REQUIRED 1	IN THIS CAS	E, WHICH WAS AC	TUALLY 288 DEGRE	ES.
3 745	THE CHECK	OUTSIT ANIBAR DE	UTATIONS ADE ALS	O DEL TELIER MA
Us Inc	TAMO DORDE	GUENT COURSE DE		1 MAI 12 (/6/11 1/1
		QUENT COURSE DE		
			MATHEMATICAL ERR	
BE FROM PI	LOT ERROR.	A ONE MINUTE		OR IN ADDITION
BE FROM PI	LOT ERROR.	A ONE MINUTE TURN EARLY ON L	MATHEMATICAL ERRO EG AZ TO BA PLAC	OR IN ADDITION
BE FROM PI CAUSED THE OF COURSE	LOT ERROR. PILOT TO (TOWARD TH	A ONE MINUTE TURN EARLY ON L E MAINLAND) ON	MATHEMATICAL ERRO Eg az to ba plac Legs bb-bc ánd bi	OR IN ADDITION ING THE ART LEFT E-FB. ALTHOUGH
BE FROM PI CAUSED THE OF COURSE	LOT ERROR. PILOT TO (TOWARD TH	A ONE MINUTE TURN EARLY ON L E MAINLAND) ON	MATHEMATICAL ERRO EG AZ TO BA PLAC	OR IN ADDITION ING THE ART LEFT E-FB. ALTHOUGH
BE FROM PICAUSED THE OF COURSE	LOT ERROR. PILOT TO (TOWARD TH	A ONE MINUTE TURN EARLY ON L E MAINLAND) ON HAT THE WEATHER	MATHEMATICAL ERRO Eg az to ba plac Legs bb-bc ánd bi	OR IN ADDITION ING THE ART LEFT E-FB. ALTHOUGH R NAVIGATION
BE FROM PICAUSED THE PILOT (BROKEN CL	CLOT ERROR. PILOT TO (TOWARD THE CONTENDS TO OUD CONDIT	A ONE MINUTE TURN EARLY ON L E MAINLAND) ON : HAT THE WEATHER ION) I FEEL HE	MATHEMATICAL ERRO EG AZ TO BA PLAC LEGS BB-BC AND BI WAS SUITABLE FOR	OR IN ADDITION ING THE ART LEFT E-FB. ALTHOUGH R NAVIGATION FLIGHT LOG TIMES
BE FROM PICAUSED THE OF COURSE THE PILOT (BROKEN CL	COT ERROR. PILOT TO (TOWARD THE CONTENDS TO OUD CONDITE GS WITHOUT	A ONE MINUTE TURN EARLY ON L E MAINLAND) ON I HAT THE WEATHER ION) I FEEL HE REFERENCE TO L	MATHEMATICAL ERRO EG AZ TO BA PLAC LEGS BB-BC AND BI WAS SUITABLE FOR SIMPLY FLEW HIS I	OR IN ADDITION ING THE ART LEFT E-FB. ALTHOUGH R NAVIGATION FLIGHT LOG TIMES DINTS.
BE FROM PICAUSED THE OF COURSE THE PILOT (BROKEN CLAND HEADING	LOT ERROR. PILOT TO (TOWARD THE CONTENDS TO OUD CONDITE GS WITHOUT HAS MADE	A ONE MINUTE TURN EARLY ON L E MAINLAND) ON : HAT THE WEATHER ION) I FEEL HE REFERENCE TO L E NO EFFORT TO	MATHEMATICAL ERRO EG AZ TO BA PLAC LEGS BB-BC AND BI WAS SUITABLE FOR SIMPLY FLEW HIS I	OR IN ADDITION ING THE ART LEFT E-FB. ALTHOUGH R NAVIGATION FLIGHT LOG TIMES DINTS.

BT